



Calibration look up procedure links & information

GM <https://tis2web.service.gm.com/tis2web/>

GM Programming symbol
If the module in question has this symbol it will
require programming when replaced.



Chrysler <https://www.techauthority.com/> PDF document

Honda https://techinfo.honda.com/rjanisis/pubs/web/RJAAI001_TOOLS1.htm

PCM 37805-_____ TCM 21802-_____ Note proper format when entering
onto website look up page.

Ford <https://www.motorcraftservice.com/> PCM / ECM identifier -12A650-

Toyota, Kia / Hyundai, & Nissan

Calibrations are listed in TSB's

Nissan ECM prefix:
23710-_____

TIPS:

- Obtain calibrations from vehicle. Locate calibrations on website or TSB using **Ctrl F** to open search bar / find menu.
- Always read all applicable SI and TSB information before programming.
- Check for aftermarket accessories spliced into network. IE radios, remote start.

Check out: <http://handsonautotraining.com/>



YouTube Brian Mann



brianmann.et@gmail.com